



Shaun Williams
Senior Aviation Accident Investigator
Office of Aviation Safety - Central Region

Date: April 27, 2023

Subject: CEN22FA383 Air Traffic Control Communications

When the accident airplane was about 28 miles west of Peoria International Airport (PIA), the pilot established communications with air traffic control (ATC) and reported inbound for PIA with the current weather information. The controller advised the pilot to enter a right downwind leg for runway 22. When the airplane was about 10 miles west of PIA, the pilot informed ATC that the engine lost all power. When queried if they would be able to reach PIA, the pilot stated that they would be unable. No further communications were received.

END